## PORT AUTHORITY.

# **Pincheck Easy Care Shirt**

## PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Body Length	28	29	30	31	32	33	33.5	34
Chest Width	20	21.5	23	24.5	26	27.5	29.5	31.5
Sleeve Length	31.25	35	35.75	36.5	37.25	38	38.75	39.5
Neck	17	17	17.5	18	19	19.75	20.5	21.25

CHEST WIDTH BODY LENGTH AT BACK

Measured across the chest one inch below armhole when laid flat.

Measured from high point shoulder to finished hem at back.

NECK SLEEVE LENGTH

Measure from center of button to end of buttonhole. Start at center of neck and measure down shoulder, down sleeve to hem.

## SIZE CHART

	XS	S	М	L	XL	2XL	3XL	4XL
Chest Width	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57
Neck	14.5 - 15	15 - 15.5	15.5 - 16	16 - 16.5	16.5 - 17	17 - 17.5	17.5 - 18	18 - 18.5
Arm	30.5	32	34	35	36.5	37.5	38.5	39.5

## CHEST WIDTH

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

## **NECK**

Measure around the fullest part of the neck at the base.

## ARM

Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.